



Toerental-tabel gatenzagen

Speed Chart for Hole Saws | Tableau des Vitesses pour Scies Cloche

TOEREN PER MINUUT					
REVOLUTIONS PER MINUTE TOURS PAR MINUTE					
Diameter MM Diamètre MM	Kunststof Plastic Plastique	RVS SS Inox	Staal Steel Acier	Aluminium	Hout Wood Bois
14	580	300	580	900	3000
16	550	275	550	825	3000
17	500	250	500	750	3000
19	460	230	460	690	3000
20	440	220	440	675	3000
21	415	210	425	660	3000
22	390	195	390	580	3000
24	365	185	360	555	2700
25	350	175	350	525	2700
27	325	160	325	480	2700
29	300	150	300	450	2400
30	285	145	285	425	2400
32	275	140	275	410	2400
33	260	135	260	390	2400
35	250	125	250	375	2400
37	240	120	240	360	2400
38	230	115	230	345	2400
40	220	110	220	330	2100
41	210	105	210	315	2100
43	205	100	205	305	2100
44	195	95	195	295	2100
46	190	95	190	285	2100
48	180	90	180	270	2100
51	170	85	170	255	2000
52	165	80	165	240	2000
54	160	80	160	240	2000
56	155	80	155	240	2000
57	150	75	150	225	2000
59	145	75	145	225	2000
60	140	70	140	220	2000
64	135	65	135	205	1850
65	130	65	130	200	1850
67	130	65	130	195	1800
68	125	65	130	190	1800
70	125	60	125	185	1800
73	120	60	120	180	1800
76	115	55	115	170	1800
79	110	55	110	165	1500
83	105	50	105	155	1500
86	100	50	100	150	1500
89	95	45	95	145	1200
92	90	45	95	140	1200
95	90	45	90	135	1200
98	90	45	90	135	1200
102	85	40	85	130	1000
105	80	40	80	120	1000
108	80	40	80	120	900
111	80	40	80	120	900
114	75	35	75	105	900
121	75	35	75	105	900
127	65	30	65	90	800
140	60	25	60	85	800
146	55	25	55	75	800
152	55	25	55	75	800
168	50	25	50	70	700
190	45	25	45	65	600
200	40	25	40	60	500
210	40	25	40	60	500